1	<u>CUSTOMER NUMBER:</u> 25268 IN THE UNITED STATES PATENT AND TRADEMARK OFFICE				
2	IN THE UNITED STATES PATENT AND TRADEMARK OFFICE				
3 4	Inventors:	Yarnykh et a	ıl.	Attorney Docket No. UNIV0217	
5	Patent No:	7,315,756		Group Art Unit: 3737	
6	Issued:	January 1, 2	008	Examiner: Mehta, Parikha Solanki	
7 8	Title: MULTI-SLICE DOUBLE INVERSION-RECOVERY BLACK-BLOOD IMAGING WITH SIMULTANEOUS SLICE RE-INVERSION				
9	NOTIFICATION OF ERRORS				
10				Bellevue, Washington 98004	
11				February 28, 2008	
12	TO THE COMMISSIONER FOR PATENTS:				
13	The following errors were found during a review of the above-referenced United States				
14	Letters Patent. These errors were either inadvertently made in the original application or occurred				
15	in the printing of the patent. Since the errors are of an obvious nature, a formal Certificate of				
16	Correction is not believed to be warranted at this time. Therefore, it is requested that this				
17	notification be placed in the U.S. Patent and Trademark Office file.				
18	Location in Par	<u>tent</u>	<u>Error</u>		
19 20	Column 5, line 19		"Nat" should readN at		
21	Column 15, line 35		"enable" should readenables		
22				Respectfully submitted,	
23					
24					
25				/ron anderson/	
26				Ronald M. Anderson	
27				Registration No. 28,829	
28					
29					
30					

31